



SYSTIMAX® Structured Connectivity Solutions

This email is for External Communication

#2003.fi.3658

8th January 2004

Fiber Patch Cord Configurable Codes

We are pleased to announce the implementation of FPC configurable patch cords. Effective November 1, 2003, Avaya Connectivity Solutions has begun accepting all standard SYSTIMAX® fiber patch cord orders in **FPC** codes. Similar to the CPC series of material IDs for the SYSTIMAX copper patch cords, the FPC codes are feature configurable, which allows customers to order fiber patch cords in specific type and length with specific connections. The series of FPC material IDs will replace the current 9-digit material IDs for all types of fiber patch cords, except for mode conditioning patch cords. This new way of specifying and ordering fiber patch cords is much more customer friendly than the current method. Instead of maintaining hundreds of Material IDs for all the possible combinations of fiber type, connector type, etc. any fiber patch cord can be configured and ordered with only the table below.

The table below shows the FPC coding scheme and ordering guide:

SYSTIMAX® Fiber Patch Cord FPC Coding Scheme and Ordering Guide									
	Fiber Type	End One	End Two	Cordage Size	# of Fibers	Jacket Type		UOM	Length
<u>FPC</u>	<u>a</u>	<u>bb</u>	<u>cc</u>	<u>d</u>	<u>e</u>	<u>f</u>	-	<u>g</u>	<u>hhh</u>
Fiber Patch Cord	X = LS 550 Z* = LS 300 H* = LS 150 W = TS M = OS MM	LC=LC SC=SC EP=STII+ MP*=MPO	LC=LC SC=SC EP=STII+ UC=none MJ=MTRJ MP*=MPO	1=0.9mm 2=1.6mm 3=3.0mm 9* = cable (> 2 fibers)	1=simplex 2=duplex A* = 12 ribbon B* = 2x12 ribbon	R= Riser H= *LSZH P* = Plenum		F=foot M= meter	0-999

Note: * These options are only available in InstaPATCH™ solution.

It should be noted that the material IDs for the mode conditioning fiber patch cords would not be converted to the FPC codes. Customers will continue to order the mode conditioning cords with the current 9-digit material ID.

Following changes will be implemented with the introduction of the FPC material IDs:

- All existing LazrSPEED® 300 fiber patch cords will be discontinued and replaced by LazrSPEED 550 fiber patch cords, which were recently introduced using the new FPC scheme. The existing LazrSPEED 300 (identified by the 9 digit material IDs) fiber patch cords will be discontinued effective March 20, 2004.
- All existing OptiSPEED® Singlemode fiber patch cords will be discontinued and replaced by TeraSPEED™ fiber patch cords, which were recently introduced using the new FPC scheme. The existing OptiSPEED SM fiber patch cord (identified by 9 digit material IDs) will be discontinued effective March 20, 2004.
- Effective immediately the nine digit Material IDs for the OptiSPEED MM fiber patch cord will be discontinued and replaced by the FPC codes. There is no product change associated with this material ID change. The existing OptiSPEED Multimode fiber patch cords identified by nine digit Material IDs can still be used.

LazrSPEED Fiber Patch cords

Old Material ID	Old Material Description	Replacement Material ID	Replacement Material Description
760000653	CLI-TZ1LC-UC-5	FPCXLCUC11-RF005	LazrSPEED 550 LC-UC .9mm Pigtail
108724956	CLI-MZ2LC-LC-E/W	FPCXLCLC22	LazrSPEED 550 LC-LC 1.6mm Duplex
108573627	CLI-MZ2LC-LC-04	FPCXLCLC22-RF004	
108573635	CLI-MZ2LC-LC-06	FPCXLCLC22-RF006	
108573643	CLI-MZ2LC-LC-10	FPCXLCLC22-RF010	
108573650	CLI-MZ2LC-LC-20	FPCXLCLC22-RF020	
108573668	CLI-MZ2LC-LC-30	FPCXLCLC22-RF030	
108573676	CLI-MZ2LC-LC-40	FPCXLCLC22-RF040	
108573684	CLI-MZ2LC-LC-50	FPCXLCLC22-RF050	
108573692	CLI-MZ2LC-LC-85	FPCXLCLC22-RF085	
108573700	CLI-MZ2LC-LC-105	FPCXLCLC22-RF105	
108725029	CLI-MZ2EP-EP E/W	FPCXEPEP22	
108688680	CLI-MZ2EP-EP-04	FPCXEPEP22-RF004	
108688136	CLI-MZ2EP-EP-06	FPCXEPEP22-RF006	
108572710	CLI-MZ2EP-EP-10	FPCXEPEP22-RF010	
108572728	CLI-MZ2EP-EP-20	FPCXEPEP22-RF020	
108572736	CLI-MZ2EP-EP-30	FPCXEPEP22-RF030	
108688144	CLI-MZ2EP-EP-40	FPCXEPEP22-RF040	
108572744	CLI-MZ2EP-EP-50	FPCXEPEP22-RF050	
108572751	CLI-MZ2EP-EP-85	FPCXEPEP22-RF085	
108572769	CLI-MZ2EP-EP-105	FPCXEPEP22-RF105	
760003244	CLI-DZ2EP-EP-E/W	FPCXEPEP32	LazrSPEED 550 STII+-STII+ 3.0mm Duplex
760003251	CLI-DZ2EP-EP-04	FPCXEPEP32-RF004	
760003269	CLI-DZ2EP-EP-06	FPCXEPEP32-RF006	
760003277	CLI-DZ2EP-EP-10	FPCXEPEP32-RF010	
760003285	CLI-DZ2EP-EP-20	FPCXEPEP32-RF020	
760003293	CLI-DZ2EP-EP-30	FPCXEPEP32-RF030	
760003301	CLI-DZ2EP-EP-40	FPCXEPEP32-RF040	
760003319	CLI-DZ2EP-EP-50	FPCXEPEP32-RF050	
108725060	CLI-FZ2EP-EP E/W	FPCXEPEP32	LazrSPEED 550 STII+-STII+ 3.0mm Duplex
108573106	CLI-FZ2EP-EP-04	FPCXEPEP32-RF004	
108573114	CLI-FZ2EP-EP-06	FPCXEPEP32-RF006	
108573122	CLI-FZ2EP-EP-10	FPCXEPEP32-RF010	
108573130	CLI-FZ2EP-EP-20	FPCXEPEP32-RF020	
108573148	CLI-FZ2EP-EP-30	FPCXEPEP32-RF030	
108573155	CLI-FZ2EP-EP-40	FPCXEPEP32-RF040	
108573163	CLI-FZ2EP-EP-50	FPCXEPEP32-RF050	
760006726	CLI-TZ1SC-UC-E/W PIGTAIL	FPCXSCUC11	LazrSPEED 550 SC-UC .9mm Pigtail
108724980	CLI-MZ2SC-SC E/W	FPCXSCSC22	LazrSPEED 550 SC-SC 1.6mm Duplex
108688102	CLI-MZ2SC-SC-04	FPCXSCSC22-RF004	
108688110	CLI-MZ2SC-SC-06	FPCXSCSC22-RF006	
108574971	CLI-MZ2SC-SC-10	FPCXSCSC22-RF010	
108574997	CLI-MZ2SC-SC-20	FPCXSCSC22-RF020	

LazrSPEED Fiber Patch cords (Continued)

Old Material ID	Old Material Description	Replacement Material ID	Replacement Material Description
108575002	CLI-MZ2SC-SC-30	FPCXSCSC22-RF030	LazrSPEED 550 SC-SC 1.6mm Duplex
108688128	CLI-MZ2SC-SC-40	FPCXSCSC22-RF040	
108575010	CLI-MZ2SC-SC-50	FPCXSCSC22-RF050	
108575028	CLI-MZ2SC-SC-85	FPCXSCSC22-RF085	
108575036	CLI-MZ2SC-SC-105	FPCXSCSC22-RF105	
760003400	CLI-DZ2SC-SC-E/W	FPCXSCSC32	LazrSPEED 550 SC-SC 3.0mm Duplex
760003418	CLI-DZ2SC-SC-04	FPCXSCSC32-RF004	
760003426	CLI-DZ2SC-SC-06	FPCXSCSC32-RF006	
760003434	CLI-DZ2SC-SC-10	FPCXSCSC32-RF010	
760003442	CLI-DZ2SC-SC-20	FPCXSCSC32-RF020	
760003459	CLI-DZ2SC-SC-30	FPCXSCSC32-RF030	
760003467	CLI-DZ2SC-SC-40	FPCXSCSC32-RF040	
760003475	CLI-DZ2SC-SC-50	FPCXSCSC32-RF050	LazrSPEED 550 SC-SC 3.0mm Duplex
108725078	CLI-FZ2SC-SC E/W	FPCXSCSC32	
108572777	CLI-FZ2SC-SC-04	FPCXSCSC32-RF004	
108572785	CLI-FZ2SC-SC-06	FPCXSCSC32-RF006	
108572793	CLI-FZ2SC-SC-10	FPCXSCSC32-RF010	
108572801	CLI-FZ2SC-SC-20	FPCXSCSC32-RF020	
108572819	CLI-FZ2SC-SC-30	FPCXSCSC32-RF030	
108572827	CLI-FZ2SC-SC-40	FPCXSCSC32-RF040	LazrSPEED 550 LC-STII+ 1.6mm Duplex
108572835	CLI-FZ2SC-SC-50	FPCXSCSC32-RF060	
108724972	CLI-MZ2LC-EP-E/W	FPCXLCEP22	
108573502	CLI-MZ2LC-EP-04	FPCXLCEP22-RF004	
108573510	CLI-MZ2LC-EP-06	FPCXLCEP22-RF006	
108573528	CLI-MZ2LC-EP-10	FPCXLCEP22-RF010	
108573536	CLI-MZ2LC-EP-20	FPCXLCEP22-RF020	
108573544	CLI-MZ2LC-EP-30	FPCXLCEP22-RF030	LazrSPEED 550 LC-SC 1.6mm Duplex
108573551	CLI-MZ2LC-EP-40	FPCXLCEP22-RF040	
108573619	CLI-MZ2LC-EP-50	FPCXLCEP22-RF060	
108724964	CLI-MZ2LC-SC-E/W	FPCXLCSC22	
108573783	CLI-MZ2LC-SC-04	FPCXLCSC22-RF004	
108573791	CLI-MZ2LC-SC-06	FPCXLCSC22-RF006	
108573809	CLI-MZ2LC-SC-10	FPCXLCSC22-RF010	
108574435	CLI-MZ2LC-SC-20	FPCXLCSC22-RF020	LazrSPEED 550 LC-MTRJ 1.6mm Duplex
108574443	CLI-MZ2LC-SC-30	FPCXLCSC22-RF030	
108574450	CLI-MZ2LC-SC-40	FPCXLCSC22-RF040	
108574468	CLI-MZ2LC-SC-50	FPCXLCSC22-RF060	
108725037	CLI-MZ2LC-MJ-E/W	FPCXLCMJ22	
108573718	CLI-MZ2LC-MJ-04	FPCXLCMJ22-RF004	
108573726	CLI-MZ2LC-MJ-06	FPCXLCMJ22-RF006	
108573734	CLI-MZ2LC-MJ-10	FPCXLCMJ22-RF010	
108573742	CLI-MZ2LC-MJ-20	FPCXLCMJ22-RF020	LazrSPEED 550 LC-MTRJ 1.6mm Duplex
108573759	CLI-MZ2LC-MJ-30	FPCXLCMJ22-RF030	

LazrSPEED Fiber Patch cords (Continued)

Old Material ID	Old Material Description	Replacement Material ID	Replacement Material Description	
108573767	CLI-MZ2LC-MJ-40	FPCXLCMJ22-RF040	LazrSPEED 550 LC-MTRJ 1.6mm Duplex	
108573775	CLI-MZ2LC-MJ-50	FPCXLCMJ22-RF060		
108725052	CLI-MZ2EP-MJ-E/W	FPCXEPMJ22	LazrSPEED 550 STII+-MTRJ 1.6mm Duplex	
108573437	CLI-MZ2EP-MJ-04	FPCXEPMJ22-RF004		
108573445	CLI-MZ2EP-MJ-06	FPCXEPMJ22-RF006		
108573452	CLI-MZ2EP-MJ-10	FPCXEPMJ22-RF010		
108573460	CLI-MZ2EP-MJ-20	FPCXEPMJ22-RF020		
108573478	CLI-MZ2EP-MJ-30	FPCXEPMJ22-RF030		
108573486	CLI-MZ2EP-MJ-40	FPCXEPMJ22-RF040		
108573494	CLI-MZ2EP-MJ-50	FPCXEPMJ22-RF060		
108725045	CLI-MZ2SC-MJ-E/W	FPCXSCMJ22		LazrSPEED 550 SC-MTRJ 1.6mm Duplex
108574476	CLI-MZ2SC-MJ-04	FPCXSCMJ22-RF004		
108574484	CLI-MZ2SC-MJ-06	FPCXSCMJ22-RF006		
108574500	CLI-MZ2SC-MJ-10	FPCXSCMJ22-RF010		
108574518	CLI-MZ2SC-MJ-20	FPCXSCMJ22-RF020		
108574526	CLI-MZ2SC-MJ-30	FPCXSCMJ22-RF030		
108574534	CLI-MZ2SC-MJ-40	FPCXSCMJ22-RF040		
108574963	CLI-MZ2SC-MJ-50	FPCXSCMJ22-RF060		
760003327	CLI-DZ2SC-EP-E/W	FPCXSCEP32	LazrSPEED 550 SC-STII+ 3.0mm Duplex	
760003335	CLI-DZ2SC-EP-04	FPCXSCEP32-RF004		
760003343	CLI-DZ2SC-EP-06	FPCXSCEP32-RF006		
760003350	CLI-DZ2SC-EP-10	FPCXSCEP32-RF010		
760003368	CLI-DZ2SC-EP-20	FPCXSCEP32-RF020		
760003376	CLI-DZ2SC-EP-30	FPCXSCEP32-RF030		
760003384	CLI-DZ2SC-EP-40	FPCXSCEP32-RF040		
760003392	CLI-DZ2SC-EP-50	FPCXSCEP32-RF050		
108724998	CLI-FZ2SC-EP E/W	FPCXSCEP32		LazrSPEED 550 SC-STII+ 3.0mm Duplex
108572843	CLI-FZ2SC-EP-04	FPCXSCEP32-RF004		
108572850	CLI-FZ2SC-EP-06	FPCXSCEP32-RF006		
108572868	CLI-FZ2SC-EP-10	FPCXSCEP32-RF010		
108572876	CLI-FZ2SC-EP-20	FPCXSCEP32-RF020		
108572884	CLI-FZ2SC-EP-30	FPCXSCEP32-RF030		
108572892	CLI-FZ2SC-EP-40	FPCXSCEP32-RF040		
108572900	CLI-FZ2SC-EP-50	FPCXSCEP32-RF050		

TeraSPEED/SM Fiber Patch cords

Old Material ID	Old Material Description	Replacement Material ID	Replacement Material Description
700010945	CLI-BS1LC-UC-5	FPCWLCUC11-RF005	TeraSPEED LC-UC .9mm Pigtail
700201379	CLI-BS1LC-UC-7	FPCWLCUC11-RF007	
700216310	CLI-BS1LC-UC-10	FPCWLCUC11-RF010	

TeraSPEED/SM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	Replacement Material ID	Replacement Material Description
700181027	CLI-MS1LC-LC-E/W	FPCWLCLC21	TeraSPEED LC-LC 1.6mm Simplex
700002637	CLI-MS1LC-LC-.67 FEET	FPCWLCLC21-RF001	
700003957	CLI-MS1LC-LC-4	FPCWLCLC21-RF004	
700003940	CLI-MS1LC-LC-5	FPCWLCLC21-RF005	
700003734	CLI-MS1LC-LC-6	FPCWLCLC21-RF006	
700003932	CLI-MS1LC-LC-8	FPCWLCLC21-RF008	
700003924	CLI-MS1LC-LC-10	FPCWLCLC21-RF010	
700003726	CLI-MS1LC-LC-15	FPCWLCLC21-RF015	
700003916	CLI-MS1LC-LC-20	FPCWLCLC21-RF020	
700003908	CLI-MS1LC-LC-25	FPCWLCLC21-RF025	
700003890	CLI-MS1LC-LC-30	FPCWLCLC21-RF030	
700003684	CLI-MS1LC-LC-35	FPCWLCLC21-RF035	
700003882	CLI-MS1LC-LC-40	FPCWLCLC21-RF040	
700003718	CLI-MS1LC-LC-50	FPCWLCLC21-RF050	
700003874	CLI-MS1LC-LC-75	FPCWLCLC21-RF075	
700003866	CLI-MS1LC-LC-100	FPCWLCLC21-RF100	
700181043	CLI-MS2LC-LC-E/W	FPCWLCLC22	TeraSPEED LC-LC 1.6mm Duplex
700003858	CLI-MS2LC-LC-4	FPCWLCLC22-RF004	
700003841	CLI-MS2LC-LC-5	FPCWLCLC22-RF005	
700003700	CLI-MS2LC-LC-6	FPCWLCLC22-RF006	
700003833	CLI-MS2LC-LC-8	FPCWLCLC22-RF008	
700003692	CLI-MS2LC-LC-10	FPCWLCLC22-RF010	
700003825	CLI-MS2LC-LC-15	FPCWLCLC22-RF015	
700003817	CLI-MS2LC-LC-20	FPCWLCLC22-RF020	
700003809	CLI-MS2LC-LC-25	FPCWLCLC22-RF025	
700003791	CLI-MS2LC-LC-30	FPCWLCLC22-RF030	
700003783	CLI-MS2LC-LC-35	FPCWLCLC22-RF035	
700003775	CLI-MS2LC-LC-40	FPCWLCLC22-RF040	
700003767	CLI-MS2LC-LC-50	FPCWLCLC22-RF050	
700003759	CLI-MS2LC-LC-75	FPCWLCLC22-RF075	
700003742	CLI-MS2LC-LC-100	FPCWLCLC22-RF100	
700011083	CLI-BS1SC-UC-5	FPCWSCUC11-RF005	
700181035	CLI-MS1SC-SC-E/W	FPCWSCSC21	TeraSPEED SC-SC 1.6mm Simplex
700171143	CLI-MS2SC-SC-E/W	FPCWSCSC22	TeraSPEED SC-SC 1.6mm Duplex
700231350	CLI-FS1SC-SC-E/W	FPCWSCSC31	TeraSPEED SC-SC 3.0mm Simplex
700011059	CLI-FS1SC-SC-04	FPCWSCSC31-RF004	
700011042	CLI-FS1SC-SC-10	FPCWSCSC31-RF010	
700231368	CLI-FS2SC-SC-E/W	FPCWSCSC32	TeraSPEED SC-SC 3.0mm Duplex
700011026	CLI-FS2SC-SC-05	FPCWSCSC32-RF005	
700011018	CLI-FS2SC-SC-10	FPCWSCSC32-RF010	
700010978	CLI-BS1EP-UC-5	FPCWEPU11-RF005	TeraSPEED STII+-UC .9mm Pigtail
700181019	CLI-MS1EP-EP-E/W	FPCWEPEP21	TeraSPEED STII+-STII+ 1.6mm Simplex
700171127	CLI-MS2EP-EP-E/W	FPCWEPEP22	TeraSPEED STII+-STII+ 1.6mm Duplex

TeraSPEED/SM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	Replacement Material ID	Replacement Material Description
700011000	CLI-FS1EP-EP-10	FPCWEPEP31-RF010	TeraSPEED STII+-STII+ 3.0mm Simplex
700231343	CLI-FS2EP-EP-E/W	FPCWEPEP32	TeraSPEED STII+-STII+ 3.0mm Duplex
700010994	CLI-FS2EP-EP-04	FPCWEPEP32-RF004	
700010986	CLI-FS2EP-EP-10	FPCWEPEP32-RF010	
700216070	CLI-MS1LC-EP-E/W	FPCWLCEP21	TeraSPEED LC-STII+ 1.6mm Simplex
700002652	CLI-MS1LC-EP-55	FPCWLCEP21-RF055	
700002645	CLI-MS1LC-EP-65	FPCWLCEP21-RF065	
700002629	CLI-MS1LC-EP-156 *	FPCWLCEP21-RF156	
700216088	CLI-MS1LC-SC-E/W	FPCWLCSC21	TeraSPEED LC-SC 1.6mm Simplex
700026057	CLI-MS1EP-SC-E/W	FPCWSCEP21	TeraSPEED SC-STII+ 1.6mm Simplex
700216104	CLI-MS2LC-EP-E/W	FPCWLCEP22	TeraSPEED LC-STII+ 1.6mm Duplex
700025406	CLI-MS2LC-SC-4	FPCWLCSC22	TeraSPEED LC-SC 1.6mm Duplex
700025414	CLI-MS2LC-SC-06	FPCWLCSC22-RF004	
700010929	CLI-MS2LC-SC-10	FPCWLCSC22-RF006	
700025612	CLI-MS2LC-SC-20	FPCWLCSC22-RF010	
700025679	CLI-MS2LC-SC-30	FPCWLCSC22-RF020	
700025737	CLI-MS2LC-SC-40	FPCWLCSC22-RF030	
700025802	CLI-MS2LC-SC-50	FPCWLCSC22-RF040	
700026248	CLI-MS2LC-SC-E/W	FPCWLCSC22-RF050	TeraSPEED SC-STII+ 1.6mm Duplex
700216096	CLI-MS2EP-SC-E/W	FPCWSCEP22	
700180995	CLI-FS1EP-SC-E/W	FPCWSCEP31	TeraSPEED SC-STII+ 3.0mm Simplex
700181001	CLI-FS2EP-SC-E/W	FPCWSCEP32	TeraSPEED SC-STII+ 3.0mm Duplex
700010937	CLI-FS2EP-SC-15	FPCWSCEP32-RF015	

OptiSPEED MM Fiber Patch cords

Old Material ID	Old Material Description	New Material ID	New Material Description
700002751	CLI-BL1LC-LC-4		No replacement
700002744	CLI-BL1LC-LC-5		
700002736	CLI-BL1LC-LC-6		
700002728	CLI-BL1LC-LC-8		
700002710	CLI-BL1LC-LC-10		
700002702	CLI-BL1LC-LC-15		
700002694	CLI-BL1LC-LC-20		
700002686	CLI-BL1LC-LC-25		
700002678	CLI-BL1LC-LC-30		
700006760	CLI-BL1LC-UC-5	FPCMLCUC11-RF005	OptiSPEED MM LC-UC .9mm Pigtail
107736878	CLI-ML1LC-LC-E/W	FPCMLCLC21	OptiSPEED MM LC-LC 1.6mm Simplex
107736704	CLI-ML1LC-LC-02	FPCMLCLC21-RF002	
107736712	CLI-ML1LC-LC-04	FPCMLCLC21-RF004	
107736720	CLI-ML1LC-LC-05	FPCMLCLC21-RF005	

OptiSPEED MM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	New Material ID	New Material Description
107736738	CLI-ML1LC-LC-06	FPCMLCLC21-RF006	OptiSPEED MM LC-LC 1.6mm Simplex
107736746	CLI-ML1LC-LC-08	FPCMLCLC21-RF008	
107736753	CLI-ML1LC-LC-10	FPCMLCLC21-RF010	
107736761	CLI-ML1LC-LC-15	FPCMLCLC21-RF015	
107736779	CLI-ML1LC-LC-20	FPCMLCLC21-RF020	
107736787	CLI-ML1LC-LC-25	FPCMLCLC21-RF025	
107736795	CLI-ML1LC-LC-30	FPCMLCLC21-RF030	
107736811	CLI-ML1LC-LC-35	FPCMLCLC21-RF035	
107736829	CLI-ML1LC-LC-40	FPCMLCLC21-RF040	
107736837	CLI-ML1LC-LC-50	FPCMLCLC21-RF050	
107736845	CLI-ML1LC-LC-75	FPCMLCLC21-RF075	
107736852	CLI-ML1LC-LC-100	FPCMLCLC21-RF100	
107737041	CLI-ML2LC-LC-E/W	FPCMLCLC22	OptiSPEED MM LC-LC 1.6mm Duplex
107736886	CLI-ML2LC-LC-02	FPCMLCLC22-RF002	
107736894	CLI-ML2LC-LC-04	FPCMLCLC22-RF004	
107736910	CLI-ML2LC-LC-05	FPCMLCLC22-RF005	
107736928	CLI-ML2LC-LC-06	FPCMLCLC22-RF006	
107736936	CLI-ML2LC-LC-08	FPCMLCLC22-RF008	
107736944	CLI-ML2LC-LC-10	FPCMLCLC22-RF010	
107736951	CLI-ML2LC-LC-15	FPCMLCLC22-RF015	
107736969	CLI-ML2LC-LC-20	FPCMLCLC22-RF020	
107736977	CLI-ML2LC-LC-25	FPCMLCLC22-RF025	
107736985	CLI-ML2LC-LC-30	FPCMLCLC22-RF030	
107736993	CLI-ML2LC-LC-35	FPCMLCLC22-RF035	
107737009	CLI-ML2LC-LC-40	FPCMLCLC22-RF040	
107737017	CLI-ML2LC-LC-50	FPCMLCLC22-RF050	
108586660	CLI-ML2LC-LC-55	FPCMLCLC22-RF075	
107737025	CLI-ML2LC-LC-75	FPCMLCLC22-RF100	
107737033	CLI-ML2LC-LC-100	FPCMLCLC22-RF018	
700002876	CLI-BL1SC-SC-10		OptiSPEED MM SC-UC .9mm Pigtail
700003353	CLI-BL1SC-UC-5	FPCMSCUC11-RF005	
700003296	CLI-BL1SC-UC-7	FPCMSCUC11-RF007	
700003205	CLI-BL1SC-UC-17	FPCMSCUC11-RF017	
700002777	CLI-BL1SC-UC-20	FPCMSCUC11-RF020	
700003098	CLI-BL1SC-UC-35	FPCMSCUC11-RF035	OptiSPEED MM SC-SC 1.6mm Simplex
107671125	CLI-ML1SC-SC-E/W	FPCMSCSC21	
107653990	CLI-ML1SC-SC-02	FPCMSCSC21-RF002	
107670994	CLI-ML1SC-SC-04	FPCMSCSC21-RF004	
107671000	CLI-ML1SC-SC-05	FPCMSCSC21-RF005	
107671018	CLI-ML1SC-SC-10	FPCMSCSC21-RF010	
107671026	CLI-ML1SC-SC-15	FPCMSCSC21-RF015	
107671034	CLI-ML1SC-SC-20	FPCMSCSC21-RF020	
107671042	CLI-ML1SC-SC-25	FPCMSCSC21-RF025	

OptiSPEED MM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	New Material ID	New Material Description
107671059	CLI-ML1SC-SC-30	FPCMSCSC21-RF030	OptiSPEED MM SC-SC 1.6mm Simplex
107671067	CLI-ML1SC-SC-35	FPCMSCSC21-RF035	
107671075	CLI-ML1SC-SC-40	FPCMSCSC21-RF040	
107671083	CLI-ML1SC-SC-45	FPCMSCSC21-RF045	
107671091	CLI-ML1SC-SC-50	FPCMSCSC21-RF050	
107671109	CLI-ML1SC-SC-75	FPCMSCSC21-RF075	
108453242	CLI-ML1SC-SC-250	FPCMSCSC21-RF250	
107671299	CLI-ML2SC-SC-E/W	FPCMSCSC22	OptiSPEED MM SC-SC 1.6mm Duplex
107671133	CLI-ML2SC-SC-02	FPCMSCSC22-RF002	
107671158	CLI-ML2SC-SC-04	FPCMSCSC22-RF004	
107671166	CLI-ML2SC-SC-05	FPCMSCSC22-RF005	
107671182	CLI-ML2SC-SC-10	FPCMSCSC22-RF010	
107671190	CLI-ML2SC-SC-15	FPCMSCSC22-RF015	
107671208	CLI-ML2SC-SC-20	FPCMSCSC22-RF020	
107671216	CLI-ML2SC-SC-25	FPCMSCSC22-RF025	
107671224	CLI-ML2SC-SC-30	FPCMSCSC22-RF030	
107671232	CLI-ML2SC-SC-35	FPCMSCSC22-RF035	
107671240	CLI-ML2SC-SC-40	FPCMSCSC22-RF040	
107671257	CLI-ML2SC-SC-45	FPCMSCSC22-RF045	
107671265	CLI-ML2SC-SC-50	FPCMSCSC22-RF050	
107671273	CLI-ML2SC-SC-75	FPCMSCSC22-RF075	
107671281	CLI-ML2SC-SC-100	FPCMSCSC22-RF100	
108510967	CLI-ML2SC-SC-160	FPCMSCSC22-RF160	
700003437	CLI-FL1SC-SC-E/W	FPCMSCSC31	
106908668	CLI-FL1SC-SC-02	FPCMSCSC31-RF002	
106908676	CLI-FL1SC-SC-04	FPCMSCSC31-RF004	
106908684	CLI-FL1SC-SC-05	FPCMSCSC31-RF005	
106908692	CLI-FL1SC-SC-10	FPCMSCSC31-RF010	
106908700	CLI-FL1SC-SC-15	FPCMSCSC31-RF015	
106908718	CLI-FL1SC-SC-20	FPCMSCSC31-RF020	
106908734	CLI-FL1SC-SC-25	FPCMSCSC31-RF025	
106908742	CLI-FL1SC-SC-30	FPCMSCSC31-RF030	
106908759	CLI-FL1SC-SC-35	FPCMSCSC31-RF035	
106908767	CLI-FL1SC-SC-40	FPCMSCSC31-RF040	
106908775	CLI-FL1SC-SC-50	FPCMSCSC31-RF050	
108449554	CLI-FL1SC-SC-55	FPCMSCSC31-RF055	
108515149	CLI-FL1SC-SC-60	FPCMSCSC31-RF060	
106908783	CLI-FL1SC-SC-75	FPCMSCSC31-RF075	
108480195	CLI-FL1SC-SC-85	FPCMSCSC31-RF085	
106908791	CLI-FL1SC-SC-100	FPCMSCSC31-RF100	
108525510	CLI-FL1SC-SC-150	FPCMSCSC31-RF150	
760003780	CLI-DL2SC-SC-E/W	FPCMSCSC32	OptiSPEED MM SC-SC 3.0mm Duplex
760003798	CLI-DL2SC-SC-04	FPCMSCSC32-RF004	

OptiSPEED MM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	New Material ID	New Material Description
760003806	CLI-DL2SC-SC-06	FPCMSCSC32-RF006	OptiSPEED MM SC-SC 3.0mm Duplex
760003814	CLI-DL2SC-SC-10	FPCMSCSC32-RF010	
760003822	CLI-DL2SC-SC-15	FPCMSCSC32-RF015	
760003830	CLI-DL2SC-SC-20	FPCMSCSC32-RF020	
760003848	CLI-DL2SC-SC-25	FPCMSCSC32-RF025	
760003855	CLI-DL2SC-SC-30	FPCMSCSC32-RF030	
760003863	CLI-DL2SC-SC-35	FPCMSCSC32-RF035	
760003871	CLI-DL2SC-SC-40	FPCMSCSC32-RF040	
760003889	CLI-DL2SC-SC-50	FPCMSCSC32-RF050	
700003429	CLI-FL2SC-SC-E/W	FPCMSCSC32	
107122616	CLI-FL2SC-SC-02	FPCMSCSC32-002	
107122624	CLI-FL2SC-SC-04	FPCMSCSC32-004	
107122632	CLI-FL2SC-SC-05	FPCMSCSC32-005	
107122640	CLI-FL2SC-SC-10	FPCMSCSC32-010	
107122657	CLI-FL2SC-SC-15	FPCMSCSC32-015	
107122665	CLI-FL2SC-SC-20	FPCMSCSC32-020	
107122673	CLI-FL2SC-SC-25	FPCMSCSC32-025	
107122681	CLI-FL2SC-SC-30	FPCMSCSC32-030	
107122699	CLI-FL2SC-SC-35	FPCMSCSC32-035	
700002603	CLI-FL2SC-SC-37	FPCMSCSC32-037	
107122707	CLI-FL2SC-SC-40	FPCMSCSC32-040	
108447129	CLI-FL2SC-SC-45	FPCMSCSC32-045	
107122715	CLI-FL2SC-SC-50	FPCMSCSC32-050	
108449729	CLI-FL2SC-SC-55	FPCMSCSC32-055	
107122723	CLI-FL2SC-SC-75	FPCMSCSC32-075	
107122731	CLI-FL2SC-SC-100	FPCMSCSC32-100	
108437799	CLI-FL2SC-SC-160	FPCMSCSC32-160	
700006794	CLI-BL1EP-UC-1	FPCMEPUC11-RF001	OptiSPEED MM STII+-UC .9mm Pigtail
700006786	CLI-BL1EP-UC-5	FPCMEPUC11-RF005	
700006778	CLI-BL1EP-UC-20	FPCMEPUC11-RF020	
107487118	CLI-ML1EP-EP-E/W	FPCMEPEP21	OptiSPEED MM STII+-STII+ 1.6mm Simplex
107486953	CLI-ML1EP-EP-4	FPCMEPEP21-RF004	
107486961	CLI-ML1EP-EP-5	FPCMEPEP21-RF005	
107486979	CLI-ML1EP-EP-6	FPCMEPEP21-RF006	
107486995	CLI-ML1EP-EP-10	FPCMEPEP21-RF010	
107487019	CLI-ML1EP-EP-15	FPCMEPEP21-RF015	
107487027	CLI-ML1EP-EP-20	FPCMEPEP21-RF020	
107487043	CLI-ML1EP-EP-25	FPCMEPEP21-RF025	
107487050	CLI-ML1EP-EP-30	FPCMEPEP21-RF030	
107487274	CLI-ML2EP-EP-E/W	FPCMEPEP22	OptiSPEED MM STII+-STII+ 1.6mm Duplex
107487126	CLI-ML2EP-EP-2	FPCMEPEP22-RF002	
107487134	CLI-ML2EP-EP-4	FPCMEPEP22-RF004	
107487142	CLI-ML2EP-EP-5	FPCMEPEP22-RF005	

OptiSPEED MM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	New Material ID	New Material Description
107487159	CLI-ML2EP-EP-6	FPCMEPEP22-RF006	OptiSPEED MM STII+-STII+ 1.6mm Duplex
107487167	CLI-ML2EP-EP-8	FPCMEPEP22-RF008	
107487175	CLI-ML2EP-EP-10	FPCMEPEP22-RF010	
107487183	CLI-ML2EP-EP-15	FPCMEPEP22-RF015	
107487191	CLI-ML2EP-EP-20	FPCMEPEP22-RF020	
107487209	CLI-ML2EP-EP-25	FPCMEPEP22-RF025	
107487217	CLI-ML2EP-EP-30	FPCMEPEP22-RF030	
107487225	CLI-ML2EP-EP-35	FPCMEPEP22-RF035	
107487233	CLI-ML2EP-EP-40	FPCMEPEP22-RF040	
107487241	CLI-ML2EP-EP-50	FPCMEPEP22-RF050	
107487258	CLI-ML2EP-EP-75	FPCMEPEP22-RF075	
107487266	CLI-ML2EP-EP-100	FPCMEPEP22-RF100	
108510975	CLI-ML2EP-EP-160	FPCMEPEP22-RF160	
700002835	CLI-FL1EP-EP-E/W	FPCMEPEP31	OptiSPEED MM STII+-STII+ 3.0mm Simplex
107150153	CLI-FL1EP-EP-02	FPCMEPEP31-RF002	
107150161	CLI-FL1EP-EP-04	FPCMEPEP31-RF004	
107150179	CLI-FL1EP-EP-06	FPCMEPEP31-RF006	
107150187	CLI-FL1EP-EP-08	FPCMEPEP31-RF008	
107150195	CLI-FL1EP-EP-10	FPCMEPEP31-RF010	
107150203	CLI-FL1EP-EP-15	FPCMEPEP31-RF015	
107150211	CLI-FL1EP-EP-20	FPCMEPEP31-RF020	
107150229	CLI-FL1EP-EP-25	FPCMEPEP31-RF025	
107150237	CLI-FL1EP-EP-30	FPCMEPEP31-RF030	
107150245	CLI-FL1EP-EP-35	FPCMEPEP31-RF035	
107150252	CLI-FL1EP-EP-40	FPCMEPEP31-RF040	
107150260	CLI-FL1EP-EP-50	FPCMEPEP31-RF050	
107150278	CLI-FL1EP-EP-75	FPCMEPEP31-RF075	
107150286	CLI-FL1EP-EP-100	FPCMEPEP31-RF100	
108470121	CLI-FL1EP-EP-225	FPCMEPEP31-RF225	
760003566	CLI-DL2EP-EP-E/W	FPCMEPEP32	OptiSPEED MM STII+-STII+ 3.0mm Duplex
760003574	CLI-DL2EP-EP-04	FPCMEPEP32-RF004	
760003582	CLI-DL2EP-EP-06	FPCMEPEP32-RF006	
760003590	CLI-DL2EP-EP-10	FPCMEPEP32-RF010	
760003608	CLI-DL2EP-EP-15	FPCMEPEP32-RF015	
760003616	CLI-DL2EP-EP-20	FPCMEPEP32-RF020	
760003624	CLI-DL2EP-EP-25	FPCMEPEP32-RF025	
760003632	CLI-DL2EP-EP-30	FPCMEPEP32-RF030	
760003640	CLI-DL2EP-EP-35	FPCMEPEP32-RF035	
760003657	CLI-DL2EP-EP-40	FPCMEPEP32-RF040	
760003665	CLI-DL2EP-EP-50	FPCMEPEP32-RF050	
700002827	CLI-FL2EP-EP-E/W	FPCMEPEP32	OptiSPEED MM STII+-STII+ 3.0mm Duplex
107150302	CLI-FL2EP-EP-02	FPCMEPEP32-RF002	
107150310	CLI-FL2EP-EP-04	FPCMEPEP32-RF004	

OptiSPEED MM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	New Material ID	New Material Description
107150328	CLI-FL2EP-EP-06	FPCMEPEP32-RF006	OptiSPEED MM STII+-STII+ 3.0mm Duplex
107150336	CLI-FL2EP-EP-08	FPCMEPEP32-RF008	
107150344	CLI-FL2EP-EP-10	FPCMEPEP32-RF010	
107150351	CLI-FL2EP-EP-15	FPCMEPEP32-RF015	
107150369	CLI-FL2EP-EP-20	FPCMEPEP32-RF020	
107150377	CLI-FL2EP-EP-25	FPCMEPEP32-RF025	
107150385	CLI-FL2EP-EP-30	FPCMEPEP32-RF030	
107150393	CLI-FL2EP-EP-35	FPCMEPEP32-RF035	
107150401	CLI-FL2EP-EP-40	FPCMEPEP32-RF040	
107150419	CLI-FL2EP-EP-50	FPCMEPEP32-RF050	
108584160	CLI-FL2EP-EP-70	FPCMEPEP32-RF070	
107150427	CLI-FL2EP-EP-75	FPCMEPEP32-RF075	
107150435	CLI-FL2EP-EP-100	FPCMEPEP32-RF100	
108430489	CLI-FL2EP-EP-150	FPCMEPEP32-RF150	
108470113	CLI-FL2EP-EP-165	FPCMEPEP32-RF165	
108485939	CLI-FL2EP-EP-170	FPCMEPEP32-RF170	
108485913	CLI-FL2EP-EP-175	FPCMEPEP32-RF175	
108434002	CLI-FL2EP-EP-200	FPCMEPEP32-RF200	
108520404	CLI-FL2EP-EP-225	FPCMEPEP32-RF225	
108448937	CLI-FL2EP-EP-240	FPCMEPEP32-RF240	
108448960	CLI-FL2EP-EP-370	FPCMEPEP32-RF370	
108449521	CLI-FL2EP-EP-380	FPCMEPEP32-RF380	
107815979	CLI-ML1LC-EP-E/W	FPCMLCEP21	OptiSPEED MM LC-STII+ 1.6mm Simplex
108108564	CLI-ML1LC-EP-04	FPCMLCEP21-RF004	
108108572	CLI-ML1LC-EP-05	FPCMLCEP21-RF005	
108108580	CLI-ML1LC-EP-06	FPCMLCEP21-RF006	
108108598	CLI-ML1LC-EP-08	FPCMLCEP21-RF008	
108108606	CLI-ML1LC-EP-10	FPCMLCEP21-RF010	
108108614	CLI-ML1LC-EP-15	FPCMLCEP21-RF015	
108108622	CLI-ML1LC-EP-20	FPCMLCEP21-RF020	
108108630	CLI-ML1LC-EP-25	FPCMLCEP21-RF025	
108108648	CLI-ML1LC-EP-30	FPCMLCEP21-RF030	
108108655	CLI-ML1LC-EP-35	FPCMLCEP21-RF035	
108108663	CLI-ML1LC-EP-40	FPCMLCEP21-RF040	
108108671	CLI-ML1LC-EP-50	FPCMLCEP21-RF050	
108108689	CLI-ML1LC-EP-75	FPCMLCEP21-RF075	
108108697	CLI-ML1LC-EP-100	FPCMLCEP21-RF100	
107815995	CLI-ML1LC-SC-E/W	FPCMLCSC21	OptiSPEED MM LC-SC 1.6mm Simplex
108113713	CLI-ML1LC-SC-05	FPCMLCSC21-RF005	
108113721	CLI-ML1LC-SC-06	FPCMLCSC21-RF006	
108113739	CLI-ML1LC-SC-08	FPCMLCSC21-RF008	
108113747	CLI-ML1LC-SC-10	FPCMLCSC21-RF010	
108113754	CLI-ML1LC-SC-15	FPCMLCSC21-RF015	

OptiSPEED MM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	New Material ID	New Material Description
108113762	CLI-ML1LC-SC-20	FPCMLCSC21-RF020	OptiSPEED MM LC-SC 1.6mm Simplex
108113770	CLI-ML1LC-SC-25	FPCMLCSC21-RF025	
108113788	CLI-ML1LC-SC-30	FPCMLCSC21-RF030	
108113796	CLI-ML1LC-SC-35	FPCMLCSC21-RF035	
108113804	CLI-ML1LC-SC-40	FPCMLCSC21-RF040	
108113812	CLI-ML1LC-SC-50	FPCMLCSC21-RF050	
108113820	CLI-ML1LC-SC-75	FPCMLCSC21-RF075	
108113838	CLI-ML1LC-SC-100	FPCMLCSC21-RF100	
107755480	CLI-ML1EP-SC-E/W	FPCMSCEP21	
107755498	CLI-ML1EP-SC-02	FPCMSCEP21-RF002	
107755506	CLI-ML1EP-SC-04	FPCMSCEP21-RF004	
107755522	CLI-ML1EP-SC-06	FPCMSCEP21-RF006	
107755530	CLI-ML1EP-SC-08	FPCMSCEP21-RF008	
107755548	CLI-ML1EP-SC-10	FPCMSCEP21-RF010	
107755563	CLI-ML1EP-SC-15	FPCMSCEP21-RF015	
107755571	CLI-ML1EP-SC-20	FPCMSCEP21-RF020	
107755589	CLI-ML1EP-SC-25	FPCMSCEP21-RF025	
107755597	CLI-ML1EP-SC-30	FPCMSCEP21-RF030	
107755605	CLI-ML1EP-SC-35	FPCMSCEP21-RF035	
107755613	CLI-ML1EP-SC-40	FPCMSCEP21-RF040	
107755621	CLI-ML1EP-SC-45	FPCMSCEP21-RF045	
107755639	CLI-ML1EP-SC-50	FPCMSCEP21-RF050	
107755654	CLI-ML1EP-SC-75	FPCMSCEP21-RF075	
107755662	CLI-ML1EP-SC-100	FPCMSCEP21-RF100	
107816001	CLI-ML2LC-SC-E/W	FPCMLCSC22	OptiSPEED MM LC-SC 1.6mm Duplex
108584137	CLI-ML2LC-SC-3	FPCMLCSC22-RF003	
108072406	CLI-ML2LC-SC-04	FPCMLCSC22-RF004	
108108929	CLI-ML2LC-SC-5	FPCMLCSC22-RF005	
108072414	CLI-ML2LC-SC-06	FPCMLCSC22-RF006	
108108952	CLI-ML2LC-SC-8	FPCMLCSC22-RF008	
108027459	CLI-ML2LC-SC-10	FPCMLCSC22-RF010	
108072422	CLI-ML2LC-SC-15	FPCMLCSC22-RF015	
108108978	CLI-ML2LC-SC-20	FPCMLCSC22-RF020	
108108994	CLI-ML2LC-SC-25	FPCMLCSC22-RF025	
108027467	CLI-ML2LC-SC-30	FPCMLCSC22-RF030	
108109018	CLI-ML2LC-SC-35	FPCMLCSC22-RF035	
108027475	CLI-ML2LC-SC-40	FPCMLCSC22-RF040	
108109026	CLI-ML2LC-SC-50	FPCMLCSC22-RF050	
108586678	CLI-ML2LC-SC-55	FPCMLCSC22-RF055	
108584145	CLI-ML2LC-SC-60	FPCMLCSC22-RF060	
108109042	CLI-ML2LC-SC-75	FPCMLCSC22-RF075	
108109539	CLI-ML2LC-SC-100	FPCMLCSC22-RF100	
107815987	CLI-ML2LC-EP-E/W	FPCMLCEP22	OptiSPEED MM LC-STII+ 1.6mm Duplex

OptiSPEED MM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	New Material ID	New Material Description	
108072430	CLI-ML2LC-EP-04	FPCMLCEP22-RF004	OptiSPEED MM LC-STII+ 1.6mm Duplex	
108108721	CLI-ML2LC-EP-05	FPCMLCEP22-RF005		
108072448	CLI-ML2LC-EP-06	FPCMLCEP22-RF006		
108108739	CLI-ML2LC-EP-08	FPCMLCEP22-RF008		
108072455	CLI-ML2LC-EP-10	FPCMLCEP22-RF010		
108072463	CLI-ML2LC-EP-15	FPCMLCEP22-RF015		
108474057	CLI-ML2LC-EP-16	FPCMLCEP22-RF020		
108108747	CLI-ML2LC-EP-20	FPCMLCEP22-RF025		
108108754	CLI-ML2LC-EP-25	FPCMLCEP22-RF012		
108072471	CLI-ML2LC-EP-30	FPCMLCEP22-RF030		
108108762	CLI-ML2LC-EP-35	FPCMLCEP22-RF035		
108108770	CLI-ML2LC-EP-40	FPCMLCEP22-RF040		
108108788	CLI-ML2LC-EP-50	FPCMLCEP22-RF050		
108108796	CLI-ML2LC-EP-75	FPCMLCEP22-RF075		
108108804	CLI-ML2LC-EP-100	FPCMLCEP22-RF100	OptiSPEED MM SC-STII+ 1.6mm Duplex	
107755761	CLI-ML2EP-SC-E/W	FPCMSCEP22		
107755779	CLI-ML2EP-SC-02	FPCMSCEP22-RF002		
107755787	CLI-ML2EP-SC-04	FPCMSCEP22-RF004		
107755795	CLI-ML2EP-SC-06	FPCMSCEP22-RF006		
107755803	CLI-ML2EP-SC-08	FPCMSCEP22-RF008		
107755811	CLI-ML2EP-SC-10	FPCMSCEP22-RF010		
107755829	CLI-ML2EP-SC-15	FPCMSCEP22-RF015		
107755837	CLI-ML2EP-SC-20	FPCMSCEP22-RF020		
107755845	CLI-ML2EP-SC-25	FPCMSCEP22-RF025		
107755852	CLI-ML2EP-SC-30	FPCMSCEP22-RF030		
107755860	CLI-ML2EP-SC-35	FPCMSCEP22-RF035		
107755878	CLI-ML2EP-SC-40	FPCMSCEP22-RF040		
107755886	CLI-ML2EP-SC-45	FPCMSCEP22-RF045		
107755894	CLI-ML2EP-SC-50	FPCMSCEP22-RF050		
107755902	CLI-ML2EP-SC-75	FPCMSCEP22-RF075		
107755910	CLI-ML2EP-SC-100	FPCMSCEP22-RF100		
108448770	CLI-ML2EP-SC-175	FPCMSCEP22-RF175		OptiSPEED MM LC-MTRJ 1.6mm Duplex
108448788	CLI-ML2EP-SC-300	FPCMSCEP22-RF300		
108448796	CLI-ML2EP-SC-525	FPCMSCEP22-RF525		
108462425	CLI-ML2LC-MJ-04	FPCMLCMJ22-RF004		
108462433	CLI-ML2LC-MJ-06	FPCMLCMJ22-RF006		
108462441	CLI-ML2LC-MJ-08	FPCMLCMJ22-RF008		
108462458	CLI-ML2LC-MJ-10	FPCMLCMJ22-RF010		
108462466	CLI-ML2LC-MJ-15	FPCMLCMJ22-RF015		
108462474	CLI-ML2LC-MJ-20	FPCMLCMJ22-RF020		
108462482	CLI-ML2LC-MJ-25	FPCMLCMJ22-RF025		
108462508	CLI-ML2LC-MJ-30	FPCMLCMJ22-RF030		
108462516	CLI-ML2LC-MJ-35	FPCMLCMJ22-RF035		

OptiSPEED MM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	New Material ID	New Material Description
108462524	CLI-ML2LC-MJ-40	FPCMLCMJ22-RF040	OptiSPEED MM LC-MTRJ 1.6mm Duplex
108462532	CLI-ML2LC-MJ-50	FPCMLCMJ22-RF050	
108462540	CLI-ML2LC-MJ-75	FPCMLCMJ22-RF075	
108509910	CLI-ML2EP-MJ-04	FPCMEPMJ22-RF004	OptiSPEED MM STII+-MTRJ 1.6mm Duplex
108509928	CLI-ML2EP-MJ-06	FPCMEPMJ22-RF006	
108509936	CLI-ML2EP-MJ-08	FPCMEPMJ22-RF008	
108509944	CLI-ML2EP-MJ-10	FPCMEPMJ22-RF010	
108509951	CLI-ML2EP-MJ-15	FPCMEPMJ22-RF015	
108509969	CLI-ML2EP-MJ-20	FPCMEPMJ22-RF020	
108509977	CLI-ML2EP-MJ-25	FPCMEPMJ22-RF025	
108509985	CLI-ML2EP-MJ-30	FPCMEPMJ22-RF030	
108509993	CLI-ML2EP-MJ-35	FPCMEPMJ22-RF035	
108510009	CLI-ML2EP-MJ-40	FPCMEPMJ22-RF040	
108510017	CLI-ML2EP-MJ-50	FPCMEPMJ22-RF050	
108510025	CLI-ML2EP-MJ-75	FPCMEPMJ22-RF075	OptiSPEED MM SC-MTRJ 1.6mm Duplex
108510033	CLI-ML2SC-MJ-04	FPCMSCMJ22-RF004	
108510041	CLI-ML2SC-MJ-06	FPCMSCMJ22-RF006	
108510058	CLI-ML2SC-MJ-08	FPCMSCMJ22-RF008	
108510066	CLI-ML2SC-MJ-10	FPCMSCMJ22-RF010	
108510074	CLI-ML2SC-MJ-15	FPCMSCMJ22-RF015	
108510082	CLI-ML2SC-MJ-20	FPCMSCMJ22-RF020	
108510090	CLI-ML2SC-MJ-25	FPCMSCMJ22-RF025	
108510108	CLI-ML2SC-MJ-30	FPCMSCMJ22-RF030	
108510116	CLI-ML2SC-MJ-35	FPCMSCMJ22-RF035	
108510124	CLI-ML2SC-MJ-40	FPCMSCMJ22-RF040	
108510132	CLI-ML2SC-MJ-50	FPCMSCMJ22-RF050	
108510140	CLI-ML2SC-MJ-75	FPCMSCMJ22-RF075	
107754822	CLI-FL1EP-SC-E/W	FPCMSCEP31	
107755126	CLI-FL1EP-SC-02	FPCMSCEP31-RF002	
107755142	CLI-FL1EP-SC-04	FPCMSCEP31-RF004	
107755159	CLI-FL1EP-SC-06	FPCMSCEP31-RF006	
107755167	CLI-FL1EP-SC-08	FPCMSCEP31-RF008	
107755183	CLI-FL1EP-SC-10	FPCMSCEP31-RF010	
107755191	CLI-FL1EP-SC-15	FPCMSCEP31-RF015	
107755209	CLI-FL1EP-SC-20	FPCMSCEP31-RF020	
107755217	CLI-FL1EP-SC-25	FPCMSCEP31-RF025	
107755225	CLI-FL1EP-SC-30	FPCMSCEP31-RF030	
107755233	CLI-FL1EP-SC-35	FPCMSCEP31-RF035	
107755241	CLI-FL1EP-SC-40	FPCMSCEP31-RF040	
107755258	CLI-FL1EP-SC-45	FPCMSCEP31-RF045	
107755266	CLI-FL1EP-SC-50	FPCMSCEP31-RF050	
107755274	CLI-FL1EP-SC-75	FPCMSCEP31-RF075	
107755282	CLI-FL1EP-SC-100	FPCMSCEP31-RF100	

OptiSPEED MM Fiber Patch cords (Continued)

Old Material ID	Old Material Description	New Material ID	New Material Description	
760003673	CLI-DL2EP-SC-E/W	FPCMSCEP32	OptiSPEED MM SC-STII+ 3.0mm Duplex	
760003681	CLI-DL2EP-SC-04	FPCMSCEP32-RF004		
760003699	CLI-DL2EP-SC-06	FPCMSCEP32-RF006		
760003707	CLI-DL2EP-SC-10	FPCMSCEP32-RF010		
760003715	CLI-DL2EP-SC-15	FPCMSCEP32-RF015		
760003723	CLI-DL2EP-SC-20	FPCMSCEP32-RF020		
760003731	CLI-DL2EP-SC-25	FPCMSCEP32-RF025		
760003749	CLI-DL2EP-SC-30	FPCMSCEP32-RF030		
760003756	CLI-DL2EP-SC-35	FPCMSCEP32-RF035		
760003764	CLI-DL2EP-SC-40	FPCMSCEP32-RF040		
760003772	CLI-DL2EP-SC-50	FPCMSCEP32-RF050		
107755290	CLI-FL2EP-SC-E/W	FPCMSCEP32		OptiSPEED MM SC-STII+ 3.0mm Duplex
107755308	CLI-FL2EP-SC-02	FPCMSCEP32-RF002		
107755316	CLI-FL2EP-SC-04	FPCMSCEP32-RF004		
107755324	CLI-FL2EP-SC-06	FPCMSCEP32-RF006		
107755332	CLI-FL2EP-SC-08	FPCMSCEP32-RF008		
107755340	CLI-FL2EP-SC-10	FPCMSCEP32-RF010		
107755357	CLI-FL2EP-SC-15	FPCMSCEP32-RF015		
107755365	CLI-FL2EP-SC-20	FPCMSCEP32-RF020		
107755373	CLI-FL2EP-SC-25	FPCMSCEP32-RF025		
107755381	CLI-FL2EP-SC-30	FPCMSCEP32-RF030		
107755399	CLI-FL2EP-SC-35	FPCMSCEP32-RF035		
107755415	CLI-FL2EP-SC-40	FPCMSCEP32-RF040		
107755423	CLI-FL2EP-SC-45	FPCMSCEP32-RF045		
107755431	CLI-FL2EP-SC-50	FPCMSCEP32-RF050		
107755449	CLI-FL2EP-SC-75	FPCMSCEP32-RF075		
107755464	CLI-FL2EP-SC-100	FPCMSCEP32-RF100		

Please contact your SYSTIMAX Representative, should you need additional information.